



42  
11751  
163

Site	Melbourne Regional Landfill	Job Number	11751-MRL LF GCS
Run Supervisor Name	Leigh Brown	Date	2019-07-18
Drilling Contractor	Civil group	Well ID	3A-034 / 3-498

Location Marker - Select Appropriate Location Marker

Peg	Flag	Painted Spot (Liner)	Other	Specify if Other Type
				

Quality Assurance Checklist	Yes or No?	Drawing Number
Has location been checked against design drawing?	Yes	
	Yes or No?	Notes
Is Well ID marked on location marker?	Yes	By customers surveyor
	Yes or No?	Approved Depth (m)
Has Safe Drill Depth been provided?	Yes	29
	Yes or No?	Notes
Will drill rig/well penetrate a PE capping liner?	No	
	Yes or No?	Details
Is waste control and deodoriser measures set up?	Yes	Furfy

Location Approval - Enter Names Below

Run Energy Drill Rig Support	Leigh brown
Drill Rig Operator	Andy Williams

Location Photo - A photo of the location marker must be provided before commencing drilling

